

JAN 22 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee
(County)

Located in:

Corner Code #



LIBER 2

PAGE 10

1. Public Land Survey T 7-S R 5-E M 11
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec S _____ T _____ R _____

STATE OF MICHIGAN
LENAWEE COUNTY
FILED
5 DEC 2000 9:47:11 AM
VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on November 3, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Fletcher D.S. Set post cor. Sec. 25 & 36 Willow 4 N 19 W 15 Willow 3 S 29 E 10
1883 James Blair found corner; set stone with "X" on top
1926 This corner is shown on the D.T. & I. ROW map but not tied in by distance
1969 I set a iron pipe at Blairs record distances from the South & East 1/4 corners of Sec. 25
1978 Werner Sommer found iron pipe and recorded it in Liber 4, Page 105. Nail & disc in E.P. S 75° E 60.45
2000 David Erickson found 1/2" iron pipe in monument box N 55° W 32.11 Fd. nail & shiner in NE side utility pole S 40° W 31.83 Fd. "X" S. end CMP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Nov. 3, 2000 Fd. 1/2" X 23" iron pipe in monument box. Probed in all directions but didn't find any stone. Replaced the iron pipe with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. dbl hd nail & disc in N. face EP S 80° E 60.43
Fd. nail & disc in NE face cable route post S 35° E 47.76
Fd. nail & disc in SE face EP N 55° W 32.11
Fd. "X" cut on west end of CMP S 40° W 31.81

3/4" iron pipe in monument box A-11 7-6 North 17.18

The corner is 6' west of pavement centerline

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date September 26, 2000

Signed by Glenn E. Richard Date Nov. 30, 2000
Glenn E. Richard

Surveyor's Michigan License No. 13040