

JAN 25 2000

SECTION

Filed under Remonumentation Act 345 of 1990  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 328  
STATE OF MICHIGAN  
LENAWEE COUNTY  
FILED

1 SEP 1999 5:42:39 PM

VICTORIA J. DANIELS  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in

	Located In:	Corner Code #
<u>Lenawee</u> (County)		
1. Public Land Survey	T - 8 - S R - 2 - E	M-11
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec	S T R	
	S T R	

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on August 17, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A B C D E F G H I J K L M

1														
2	6	5	4	3	2	1								
3														
4	7	8	9	10	11	12								
5														
6	18	17	16	15	14	13								
7														
8	19	20	21	22	23	24								
9														
10	30	29	28	27	26	25								
11														
12	31	32	33	34	35	36								
13														

A. Description of original monument and accessories and/or subsequent restoration:

1824 John Mullett set post cor. Sec's 25 & 36 W. Ash 12 S 19 W 13 W. Ash 10 N 63 W 27  
1922 J.L. Richard surveyed Terry Hwy. Drove gas pipe 47.50' north of bricks found at the N.W. corner of Section 31 T8S R3E.  
1986 Kenneth Suydam "Found iron SE corner Sec. 25"  
March 3, 1998 I found 1" iron pipe 47.50' north of 1/2" iron pipe (The 1/2" iron pipe was set by Roger Meinke & Timothy Mohr. They dug at A-11 T8S R3E under my direction and found soft dark spot in center of bricks 24" deep and raised with 1/2" iron pipe.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 17, 1999 I replaced the 1" iron pipe with a 30" Harrison Monument stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison Monument with Lenawee County Re-mon cap stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Set dbl hd nail & disc in R.R. tie post N 45° W 28.17  
Dbl hd nail & disc in E.P. N 15° E 117.48 feet  
Cut "X" on C.M.P. S 40° E 38.09  
Cut "X" on C.M.P. S 75° W 68.16

Iron pipe @ A-11 T8S R3E South 47.50 (G.L.O. .72=47.52')



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date July 20, 1999  
Signed by Glenn E. Richard Date Aug 23, 1999  
Surveyor's Michigan License No. 13040