

JAN 22 2001

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee
(County)


Located In:

Corner Code #



LIBER 1

PAGE 417



1. Public Land Survey T-8-S R-4-E B-13
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec S T R

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on August 11, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Wampler D.S. Set 1/4 Sec. post W. Oak 8 S 20° W 7 Elm 16 N 47 E 14
Could not find any information about this corner in either James Blair's or J.L. Richard's record.
1975 I set a iron pipe in the pavement in line of old existing fence line to the north by extending line east from a iron pipe found at the NW corner and a iron pipe at the N 1/4 corner of Section 6 T9S R4E. A 70 year old land owner claimed he saw a corner stone in the road prior to the road being paved 40± years ago.
(NOTE: J.L. Richard's record for the N 1/4 corner of Section 6 T9S R4E called for "Stake & Stone found." 1970 I found stone, bricks, & small piece of pipe and raised with 1" X 2' iron pipe) I recorded it in Liber 3, Page 302
1977 I found iron pipe 8" deep
1980 I found iron pipe in monument box which checked alignment from West and record distance
1995 Michael Bartolo found iron pipe in monument box and recorded it in Liber 5, Page 248
1999 Steven Young found iron pipe in monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 11, 2000 Found iron pipe in monument box without cover. Replaced iron pipe with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 and put on new cover.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Iron pipe in monument box @ B-1 T9S R4E West 132.47
Fd dbl hd nail & disc in 32" Maple S 75° E 129.86
Fd dbl hd nail & disc in E.P. S 45° E 151.15
NW corner of House foundation S 55° E 146.38
Dbl hd. nail & re-mon tag in E.P. S 50° W 170.06



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date August 22, 2000

Signed by Glenn E. Richard Date Sept. 15, 2000
Glenn E. Richard

Surveyor's Michigan License No. 13040