

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**  
**Luce County Remonumentation Corner**

**MAR 13 2000**

For corners in

Luce County

Located in:

Corner Code #

1. Public Land Survey

T45N R10W

E/F-5 #1

T R

T R

T R

2. Property Controlling  
in Section

S S

T R

3. Miscellaneous  
Property in Sec.

S S

T R

4. Lot No. , Recorded Plat

5. Private Claims

**LUCE COUNTY  
REGISTER OF DEEDS**

Recorded

*Liber 3 Page 900*

02-08-2000 13:00:23

*Kathy S. Mahar*  
Kathy S. Mahar, Register  
REGISTER OF DEEDS

**Register of Deeds Stamp & File Number**

I, Keith R. Waters, in a field survey on July 28, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

E/F-5 Witness Corner to Meander Corner Between Sections 9 & 16, T45N, R10W, on the East Side of Kak's Lake

1849 – Original corner established by William Ives, 67.10 chains west of the section corner at G-5, 27.10 chains west of the ¼ corner at F-5. Witnesses: Cedar 8, N30°E 10 links – Cedar 10, S20°E 25 links.

1955 – G.A.Shadko, Survey of the Public Fishing Site No. 48-4. Set a 4 inch diameter iron pipe filled with concrete and with a brass cap. Corner is shown on the east shore of Kak's Lake, 1823.5 feet west of the south ¼ corner of Section 9, T45N, R10W.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

This corner is being perpetuated as part of the Luce County Remonumentation Program.

Found a 4 inch diameter pipe, filled with concrete, with a brass cap stamped "Public Fishing Site, 48-5, 1955, T45N, R10W, 1955, Set by G.A. Shadko." The found corner is 1827.1 feet west of the ¼ corner at F-5. The above mentioned survey by Shadko shows 1823.5 feet and the GLO distance is 1788.6 feet. Accepted corner as found, while noting that it falls 34.9 feet west of the GLO position in relation to the ¼ corner at F-5.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Found a 4" diameter concrete filled pipe with a stamped brass cap at the corner location, 34.9 feet west of the record GLO position. Corner falls on the east shore of Kak's Lake, on the south side of the parking area for the Public Fishing Site. Witnesses:

Nail and tag #33142 in 8" blazed White Birch, S87°E 15.00'

Nail and tag #33142 in 16" blazed Cedar, S71°E 36.08'

Nail and tag #33142 in 6" blazed Cedar, S22°E 32.07'

Nail and tag #33142 in 10" blazed Cedar, S11°W 33.45'

Signed by Keith R. Waters

Date 12-29-99

Surveyor's Michigan License No. 33142