

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Luce County Remonumentation Corner

LUCE COUNTY
REGISTER OF DEEDS
Recorded

Liber 3 page 956

02-12-2001 09:46:33

Kathy S. Mahar, Register
REGISTER OF DEEDS

For corners in

Luce County

Located in:

Corner Code #

1. Public Land Survey

T45N R10W E-2

T
T
T
T
S
S
S
T

2. Property Controlling
in Section

S
S
S
S

3. Miscellaneous
Property in Sec.

S
S
S
S

SURVEY &
REMONUMENTATION

FEB 23 2001

4. Lot No.

, Recorded Plat

5. Private Claims

SECTION

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on October 20, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-2 1/4 Corner Common to Sections 4 & 5, Town 45 North, Range 10 West

1849 - Original corner established by William Ives.

Witnesses: Tamarack 5, N37°E 35 links - Cedar 8, S57°W 05 links.

Found no evidence subsequent restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Luce County Remonumentation Program.

Found no evidence of the original corner. Reestablished corner by single proportionate measurement on line between the section corner at E-3 to the south and the common section corner at E-1 on the township line to the north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 1/2" x 25" rebar with a stamped aluminum Luce County Remonumentation cap at the corner location, which falls approximately 30 feet north and 86 feet west of the northeast corner of a 12 foot high wood and wire deer containment fence.

Witnesses:

Nail and plastic witness tag #33142 in 12' high Cedar Fence Post, S03°E 30.10'

Nail and plastic witness tag #33142 in blazed 7" Tamarack, S76°W 8.73'

Nail and plastic witness tag #33142 in blazed 16" Cedar, N24°W 11.22'

Nail and plastic witness tag #33142 in blazed 9" Cedar, N63°E 12.54'

Nail and plastic witness tag #33142 in blazed 8" Tamarack, S31°E 7.70'

Signed by

Keith R. Waters

Date

12-29-00

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

T45N R10W E-2

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

