

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 27 T 45N R 11W	12
	S _____ T _____ R _____	(GCDB 440220)
	S 27 T 45N R 11W	13
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	(GCDB 460220)
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/05/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 27) Center-South 1/16 corner, Section 27. Not previously monumented.

(13-Sec. 27) Southeast 1/16 corner, Section 27. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 27) Established the position for the corner midway and on a straight line between Quarter
corner 1315.49' south and the intersection of 1/4 lines of Sec. 27 1315.49' north. From the
position thus established a north-south fenceline is 8.4' west.

(13-Sec. 27) Established the position for the corner at the intersection of straight lines
connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx30" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Maple N87°E 3.25' mrkd "S1/16 BT"
11" Cedar S20°W 10.9' do
9" Cedar N87°W 9.35' do
6" Balsam N18°W 25.1' do
E= 8102829.655 N= 165346.048

(13) Set 1"IDx30" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" B.Spruce S48°E 4.7' mrkd "SE1/16 BT"
6" B.Spruce N36°E 12.35' do
8" B.Spruce N59°W 11.3' do
6" B.Spruce S48°W 18.8' do
E= 8103232.554 N= 165351.976

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID DO8495: N= 169938.252 m. E= 8114556.094 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/16/2014

For the Michigan Department of Natural Resources, Forest Resources Division

