

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46 .. NR. 11 .. W

L u c e COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 3, 4, 9, 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Soft Maple (S 4 NBT) N 3° W 43 Links

10" Soft Maple (S 10 NBT) S 50° E 50 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced as set by H. Lawrence, Registered Surveyor.

Found scribed wood post, in place with Hemlock line tree 10.+chains north of corner. Line tree is down and in fair condition. Corner lies 1 chain north of road.

Corner was placed and witnessed May 25, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/14/60
REGISTERED LAND SURVEYOR
Billy D. Buckler