

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 15 T 46N R 12W	6
	S T R	(GCDB 460460)
	S 15 T 46N R 12W	2
	S T R	(GCDB 460500)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 04/02/15 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 15) Northeast 1/16 corner, Section 15. Not previously monumented.

(2-Sec. 15) East 1/16 corner between Sections 10 and 15. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 15) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners, those to the north, east, and west being monumented.

(2-Sec. 15) Established the position for the corner midway and on the Section line between Section  
corner 1330.36' east and Quarter corner 1330.36' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
7" twin Maple S82°W 8.24' mrkd "NE1/16 BT"  
9" Maple N42°W 23.38' do  
10" Balsam N44°E 2.37' do  
5" Balsam S28°E 14.76' do  
E= 8093322.157 N= 178884.533

(2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Sugar N51°E 3.78' mrkd "E1/16 BT"  
7" Sugar N07°W 17.81' do  
9" Sugar N55°W 16.63' do  
7" Sugar S55°W 15.72' do  
E= 8093313.854 N= 179290.547

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RJ1233: N= 183112.192 m. E= 8082067.781 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/10/2015

For the Michigan Department of Natural Resources, Forest Resources Division