

FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
Luce County Remonumentation Corner  
Township Corner

SECTION

For corners in

Luce County

Located in:

Corner Code #

1. Public Land Survey T45N R12W A-1 Same  
T45N R13W M-1  
T46N R13W M-13  
T46N R12W A-13 Corner
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R
4. Lot No. , Recorded Plat  
5. Private Claims

LUCE COUNTY  
REGISTER OF DEEDS  
RecordedLiber 3 Page 938  
02-12-2001 09:41:31Kathy S. Mahar, Register  
Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on July 31, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

## A. Description of original monument and accessories and/or subsequent restoration:

(A-1) Section corner common to Section 6 Township 45 North, Range 12 West, Section 1 Township 45 North, Range 13 West, Section 36 Township 46 North, Range 13 West and Section 31 Township 46 North, Range 12 West.

1841 John Burt, D.S. set post for corner. Spruce 6 S33W 24 Fir 6 N41E 13.

1960 B. Buckler P.S. 8887 set 1" pipe with 4" brass cap from original Spruce bearing tree. Witnesses established were Cedar 10" N70°W 27 lks, Cedar 6" S71°E 38 1/2lks, White Pine 15" S20°W 38 lks. (Liber A Page 416 Luce County Corner Records).

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-1) Section corner common to Section 6 Township 45 North, Range 12 West, Section 1 Township 45 North, Range 13 West, Section 36 Township 46 North, Range 13 West and Section 31 Township 46 North, Range 12 West.

This corner is being perpetuated as part of the Luce County Remonumentation Program.

Found 1" pipe with 4" brass Michigan Department of Conservation Forestry Division cap as noted above. Accepted corner position as found.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-1) Section corner common to Section 6 Township 45 North, Range 12 West, Section 1 Township 45 North, Range 13 West, Section 36 Township 46 North, Range 13 West and Section 31 Township 46 North, Range 12 West.

Corner is a 1" pipe with 4" brass Michigan Department of Conservation Forestry Division cap.

## Witnesses:

White Birch 8"	N51°E	30.28 feet
Cedar 8"	S41°E	30.83 feet
White Pine 24"	S16°W	25.67 feet (previous)
Cedar 9"	S30°W	20.85 feet

Bearings are compass bearings, corrected for declination (6° W), all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by William L. KarrDate 12/01/00

Surveyor's Michigan License No. 27450

