

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Luce

| | | |
|------------------------------------|---------------------------|---------------|
| (County) | Located In: | Corner Code # |
| 1. Public Land Survey | T <u>47N</u> R <u>12W</u> | <u>C6</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

Dec 03 1997

I, Stephan J. Szyszkoski, in a field survey on _____, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

| | | | | | | | | | | | | | |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

(C6) Quarter corner common to Section 17-18. Remonumented in 1971 by Billy D. Buckler, RLS at record bearing and distance from an original W. Pine bearing tree, found with notch and scribing visible. 1" pipe with 4" aluminum cap. 6" Soft Maple N19E 17.6', 7" Soft Maple S09E 42.4'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C6) Recovered the 1971 monument as described, a 1" ID iron pipe capped with a 4" dia. State of Michigan tablet, appropriately stamped, and at record bearing and distance from the 1971 witnesses, both recovered in good condition with blazes overgrown. Left the monument in place, marked new BH blazes on these trees, and marked two new witnesses as described below. This monument is about 50' west of a N-S trail and about 70' south of a trail SW.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C6) Found 1" pipe with 4" alum. cap.
 Blazed, scribed, and set measuring nails in the following:
 8" R. Maple N22E 17.9' "1/4S"
 9" R. Maple S06E 42.7' do
 12" R. Pine S33E 43.1' "1/4S N8T"
 10" W. Pine S70E 26.4' do
 Bearings are magnetic. Distances to nail w/tag.



Signed by Stephan J. Szyszkoski Date 4/18/00
 Surveyor's Michigan License No. 33986
 For the Michigan Department of Natural Resources - Forest Management Division