

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 49N N. R. 10W


Luce COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 28-29

CORNER MONUMENT ¼ Cor. bet. Secs. 28-29

DATE MONUMENT PLACED AND WITNESSED 9-11-70

WITNESSES TO CORNER..... 12" Hard Maple (½S NBT) N64°E 9.9'



8" W. Pine (½S NBT) S52°E 33.0

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-placed as set by Marcus Schaaf, R.L.S.  
Found 2" iron pipe in place with a Hard Maple B.T., bearing S12°W, 41 links. Tree is still growing. Face of description blaze in fair condition.  
Corner lies 1 chain south of road.

SURVEYOR'S SEAL

*Billy D. Buckler.*  
SIGNED Billy D. Buckler DATE 9-23-70  
REGISTERED LAND SURVEYOR