

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S <u>7</u> T <u>49N</u> R <u>10W</u> S <u>7</u> T <u>49N</u> R <u>10W</u> S _____ T _____ R _____	<u>15</u> <u>B4</u> _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		9		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on B4 04/07/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 7) West 1/16 corner between Sections 7 and 18. Not established in the original survey.

(B4) Center of Section 7. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 7) Established the corner on the Section line 1167.75' east of Section corner A5 and
1318.82' west of Quarter corner B5, being 19.99 chains, proportionate to the protraction given on the
original GLO plat, west of the Quarter corner.

(B4) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 5/8"x18" rebar with plastic MDNR cap
6" below the sand surface of an E-W firelane.
Set measuring nail with MDNR tag in the side of:
20" R.Pine N14W 10.8' mrkd "W1/16 BT"
11" R.Pine N42E 27.35' do
15" W.Pine S54W 13.2' do
6" Balsam S19E 11.6' do
Bearings are magnetic.

(B4) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" R.Pine N60E 20.55' mrkd "CS BT"
14" R.Pine N40W 26.3' do
6" W.Pine N79W 26.35' do
10" R.Pine S14E 7.7' do
Bearings are magnetic.

Signed by

Stephan J. Szyszkoski

Date

05/05/2011

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities



47472

47473

FORM APPROVED BY MICHIGAN STATE BOARD

1971
14, 1975
Jan., 1983
Revised Oct., 1995