

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co. Two Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>49</u> N. R. <u>11</u> E.	D-7 B-7
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 8/22 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:**
- D-7 $\frac{1}{4}$ Cor. bet. Secs: 17-20, set by Geo. H. Cannon, D.S. 1854.
Bearings were:
 Pine 22" S17 $\frac{1}{2}$ ^oW 53 lks. and W. Pine 20" N51^oE 10 lks.
 - B-7 $\frac{1}{4}$ Corner bet. Secs: 18-19, set by Geo. H. Cannon, D.S. 1854.
Bearings were:
 Balsam 8" N54^oE 25 lks. and Balsam 6" S58^oE 17 lks.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**
- D-7 Corner re-established by single proportionate measure, bet. two Sec. Corners. Corner lies 10' North of E-W county road.
 - B-7 Corner re-established by single proportionate measure, bet. two Sec. Cors. and in line with firelane to South. Corner lies in North edge of E-W road.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**
- D-7 Placed 1" pipe with 4" aluminium cap at corner.
New Bearings:
 8" Jack Pine N48^oW 12.3' and 8" Jack Pine N83^oE 20.0'
 - B-7 Buried 1" pipe with 4" aluminium cap at corner.
New Bearings:
 16" Red Pine N7^oE 27.9' and 16" Red Pine S23^oW 41.4'

SIGNED BY Billy D. Buckler DATE 1/4/73

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)