

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 9 T 49N R 11W	9
	S T R	(GCDB 360540)
	S 9 T 49N R 11W	13
	S T R	(GCDB 360520)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 9 12/15/15 do hereby state
13 12/15/15
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 24 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 9) Center-East 1/16 corner, Section 9. Not previously monumented.

(13-Sec. 9) Southeast 1/16 corner, Section 9. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 9) Established the position for the corner midway and on a straight line between Quarter corner 1324.27' east and the Center of Sec. 9 1324.27' west.

(13-Sec. 9) Established the position for the at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
5" W.Pine S46°E 17.72' mrkd "E1/16 BT"
5" Cedar N79°E 17.87' do
5" Black Sp. N12°W 19.21' do
8" Black Sp. N66°W 14.58' do
E= 8100810.180m N= 209115.596m

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
7" W.Birch N44°W 16.41' mrkd "SE1/16 BT"
10" R.Pine S78°W 10.11' do
11" R.Pine S38°E 11.07' do
10" R.Pine N66°E 6.53' do
E= 8100819.859m N= 208719.040m

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RJ0558: N= 209493.879m. E= 8083367.993m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/13/2016

For the Michigan Department of Natural Resources, Forest Resources Division, by John Nutkins, PS #52478