## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>50</u> N.R. <u>9W</u>

	Luce	COUNTY
DESCRIPTION OF CORNER _ + Cor. bet. Secs. 24-25.		
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap b	uried in Road.	·
DATE MONUMENT PLACED AND WITHESSED 8-29-63 with L.	Rubick, Aide	
WITHESSES TO CORNER 17" Red Pine ( S. N.B.T	.) S. 8° W., 153 lks.	
8* Jack Pine (‡ S. N.B.T	c.) S. 82° W., 78 lks.	
AND CINCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two Sec. Cors. Found no evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED Silly 8. Suchles DATE 1/27/64