9-

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in		,	1				
LIVINGSTON (County)	Located In:	Corner Code #		1996 NO	7 14 P I	: 2 0	
Public Land Survey Property Controlling in Section	T <u>IN R3E</u> TR_ TR TR S TR	B-9		NAMI REGIS LIVILIGS	CY HAVILAND TER OF DEED: TON COUNTY. 40843	s MI.	
3. Miscellaneous S T R R			L.S	L.S.C.#582m			
Property in Sec.	S \\			Register of D	eeds Stamp &	File Number	
4. Lot No, Record			·	ABCD	EFGH	IJKLM	
5. Private Claims			2	65-	43-		
i, Dazette Hocites, in a field survey on 10-27, 19 16 do hereby state that ur requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above wer conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumen recovered, found as expressed below:				the 5 16 15 14 13 15 14 13 15 14 13 15 15 15 15 15 15 15			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9	I I L	28 27	25 25	
on this certificate.			1	1 31 32	3334	35 36	
	20", South 16 de	and/or subsequent restora egrees West, 28 li	inks		NADILLA		
B. Description of corner evid Established by oc			eestablishing corner	:			
*Additional desc	riptions and his	torical informati	on on back of	this she	et.		
C. Description of monument	for corner and accessori	ies established to perpetua	te locating the position	on of the corne	er:		
B-9, T1N, R3F pipe, affixed Monumentation careful and former. 115 DEG. 77.88' 175 DEG. 45.70' 298 DEG. 66.45' 035 DEG. 119.91	with 2" a Corner, P.S. faithful rees SET NAIL/TAG SET NAIL/TAG SET NAIL/TAG	fia. brass 19834, in 1 stablishment of G N/S 21" WALNU G W/S 20" ELM. G SW/S 20" ELM.	cap, stan coad box, and the posit	mped "L ndisa	ivingsto: ccepted	n Ćo. as a	
Signed by	1 Habo		Date <u>Oc</u>	tober 27.	1996	or was a second	
Surveyor's Michigan License	No				6 * 6	Hitting of the Community of the Communit	

UNADILLA TOWNSHIP, TIN, R3E

B-9, SOUTH 1/4 COR. SEC. 19 AND NORTH 1/4 COR SEC. 30.

FIELD: 9-30-1996 DARRELL D. HUGHES AND ASSOCIATES.

Searched large area within road right of way East and West of occupied fence line to south. Found nothing. Ownership for lands North and South of this location is the same. 3' X 3' X 5'high concrete posts have been constructed opposite C-9, at this location and opposite A-9 at the West Township line. A fence and tree row runs south from this concrete pillar. No occupation to the North, house and buildings on line. From this concrete pillar to the North fence of Mortan Road (M-106) measures 51'. No evidence of any recent surveyors using this corner. I recommend, to the peer group, establishing this corner at the extension of the conc. post and fence line from the South with a split of the road fences that run East and West. This point will fall 1' South of the centerline of the asphalt pavement.

1825 Sylvester Sibley, U.S. Deputy Surveyor, "West between 19 and 30, 40.00 chains, set 1/4 section post". P.7

1980 Ingham County GLO fallings map, P.8

MDOT right of way map for M-106 P.9