

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Livingston
(County)

Located In:

Corner Code =#

1. Public Land Survey T 1N R 4E A-13
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

L.S.C.# 85m

Register of Deeds Stamp & File Number

Dec 22 10 13 AM '93
NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI
48843

FILED

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Darrell D. Hughes, in a field survey on December 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:

GLO: 1825
Maple 16" N86.5W 28 lks.
Ash 14" N14E 58 lks.

* Additional historical information on rear of sheet:

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. 1-1/2" pinch pipe in swamp.

SURVEY &
REMONUMENTATION

1993

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-13, T1N, R4E, PUTNAM, replaced existing corner with 1-1/4" X 36" iron pipe, affixed with 2" dia. brass cap, stamped "Livingston Co. Monumentation Corner, P.S. 19834, and is accepted as a careful and faithful reestablishment of the position of the original corner.
100 DEG. 32.73' SET NAIL/TAG S/S 12" TREE (S/S CLUMP OF 5)
180 DEG. 38.75' SET NAIL/TAG W/S 10" TREE
250 DEG. 26.58' SET NAIL/TAG S/S 10" TREE
040 DEG. 17.31' SET NAIL/TAG SE/S TWIN 12" TREE (LEANS 30 DEG. NW)

Signed by Darrell D. Hughes
Surveyor's Michigan License No. 19834

Approved by Liv Co. Board Group: Nov. 03, 1993
Date 12-21-93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

UNADILLA TOWNSHIP, T1N, R3E

M-13, SE CORNER SEC. 36

FIELD 10-21-93

Fd. 1-1/2'' pinch pipe in swamp under 12" of water. Steel "T" fence post next to iron pipe, also under water. No evidence of occupation except for downed wire fence at shore of swamp, 100' North. Latest witness (1959 Atwell-Hicks) fit existing trees and stumps (+/-). no nails fd.

1925, Grant Dunning, platted "ISLAND LAKE SHORES" subdivision. "...Fd. old stake. set 2" gas pipe, 3' long. S.2E.7" maple (old mark) 13.7'

1959, Atwell-Hicks, Fd. 3/4" pipe badly rusted for SE cor. Sec. 36, Reset with 1" pinch pipe, 120' S. into swamp. steel fence post beside corner.

1967, DNR land cor. record. 1" iron pipe, fd. , this cor recovered using notes from Herald Hamill, Plymouth, Mi.

1986, Atwell-Hicks show corner in survey on Half Moon Lake, Washtenaw Co., same witness' as 1959.

Corner is in Maple swamp, standing water 1'-2' deep with vegetation hillocks and maple trees 10" to 24". corner access is through locked gates on private property, off Patterson Lake Road.