SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

Filing Requirement	of Act 74, Mich. P.A. 1970
For corners in	1999 JUN -4 P 12: 55
LIVINGSTON Located In: Corner ( (County)	NANCY HAVILAND REGISTER OF DEEDS
TRT_R	LIVINGSTON COUNTY. MI. 48843
2. Property Controlling in Section       S T R	L.S.C. #1023m  Register of Deeds Stamp & File Number
Property in Sec. S TR	Kegister of Deeds Staining 1 10 1
4. Lot No, Recorded Plat	A B C D E F G H I J K L M  2 6 5 4 3 2 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
I JACK K SMITH, in a field survey on MARCH 22, 19 99 do he of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 regulations and rules therefore as required in the current manual of survey instruction of the Interior, Bureau of Land Management or by a decree of a Court of Law and for lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of I Court of Law; established, re-established, monumented, recovered, found as expressed	ns of the United States Department that the corner points mentioned in and Surveyors or by a Decree of a libelow:
NOTE: Not more than 2 corners, all in the same town and range, may be record on this certificate.	30 30 29 28 27 26 25 11 20 30 30 30 30 30 30 30 30 30 30 30 30 30
	12 31 32 33 34 35 35 35 35 35 35 35 35 35 35 35 35 35
A. Description of original monument and accessories and/or subsequen	t restoration:
GLO 1825 SIBLEY SET POST B. OAK 13 N 83 W 62 (40.9') B. OAK 11 N 54 E 30 (19.8')	
B. Description of corner evidence found and/or method applied in rest	toring or reestablishing corner:
FOUND A 1/2" REROD WITH BOSS CAP. THIS POSITION IS	THE ONLY ONE THAT APPEARS TO HAVE BEEN USED.
	· · · · · · · · · · · · · · · · · · ·
C. Description of monument for corner and accessories established to perpetuate l	TIN PAR DUTNIAM TOWNSHIP LIVINGSTON COUNTY, MICHIGAN:
RESET FOUND 1/2" REROD WITH 1 1/4" X 36" STEEL PHY WITH SURVEYOR #35999 @ 1/4 FOOT ABOVE THE SURFA	CE OF SURROUNDING GROUND.
N10°E NAIL WITH LIVINGSTON COUNTY REMON TAG EAST NAIL WITH LIVINGSTON COUNTY REMON TAG SOUTH NAIL WITH LIVINGSTON COUNTY REMON TAG N15°W NAIL WITH LIVINGSTON COUNTY REMON TAG	IN EAST SIDE 12" POPLAR IN EAST SIDE 6" OAK  18.97  PROFESSIONAL
Signed by fall & Amo	Date 3-21-1999 SURVEYO No. 35999
Surveyor's Michigan License No. 35999	AND
	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN REVISIO MAY 14,1973 REVISED JAN, 1983 REVISED OCT, 1995

PA. 345 1980, APPROVED BY LANGSTON COUNTY
PEER GROUP ON 3-3-/999 CO. REP