

# SURVEY & REMONUMENTATION

FEB 26 2001

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

<u>LIVINGSTON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>1</u> N R <u>4</u> E	
	T <u>  </u> R <u>  </u>	
	T <u>  </u> R <u>  </u>	
	T <u>  </u> R <u>  </u>	
2. Property Controlling in Section	S <u>  </u> T <u>  </u> R <u>  </u>	
	S <u>  </u> T <u>  </u> R <u>  </u>	
3. Miscellaneous	S <u>16</u> T <u>1</u> N R <u>4</u> E	<u>001</u> ✓
Property in Sec.	S <u>16</u> T <u>1</u> N R <u>4</u> E	<u>002</u>
4. Lot No. <u>      </u> , Recorded Plat <u>      </u>		
5. Private Claims <u>      </u>		

2000 SEP 28 1A 9:18

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

LSC #1276m

Register of Deeds Stamp & File Number

I, JACK K. SMITH, in a field survey on AUGUST 25, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 JOSEPH WAMPLER SET POST  
POST IN POND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-05 NO CORNER WAS PLACED DUE TO LAKE. THE ONLY POSITION USED PREVIOUSLY HAS BEEN AT 1/2 THE DISTANCE ON LINE BETWEEN E-05 AND G-05. SET 2 REFERENCE MONUMENTS PLACED EASTERLY AND SOUTHERLY OF COMPUTED POSITION OF F-05 ON LINE WITH E-05 AND G-05.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 001

EASTERLY REFERENCE MONUMENT W/ BRASS REMON WITNESS CAP 13' SOUTH OF CENTERLINE +/- OF DAM TRAIL (ON LINE BETWEEN F-05 AND G-05 AND DISTANT S86°57'31"E 240.00 FEET FROM THE COMPUTED POSITION OF F-05)

S50°W SPIKE AND REMON TAG ON NORTH SIDE OF 8" TWIN OAKS	50.57'
S70°W MAG NAIL IN TOP, CENTER OF FIRST STEEL POST SOUTH OF TRAIL	25.92'
N80°W MAG NAIL IN TOP, CENTER OF FIRST STEEL POST NORTH OF TRAIL	32.20'

- 002

SOUTHERLY REFERENCE MONUMENT W/ BRASS REMON WITNESS CAP 9' SOUTH OF CENTERLINE +/- OF DAM TRAIL (ON LINE BETWEEN F-05 AND F-06 AND DISTANT S00°08'07"W 350.00 FEET FROM THE COMPUTED LOCATION OF F-05)

S40°E CENTER LINE OF 5 FOOT HIGH 2" STEEL POST	21.77'
S30°W SPIKE AND REMON TAG ON NORTH SIDE OF 14" POPLAR	66.95'
S70°W SPIKE AND REMON TAG ON SOUTH SIDE OF 14" POPLAR	86.45'
WEST SOUTHEAST CORNER OF CONCRETE DAM OUTLET STRUCTURE	86.15'

Signed by

Date 9-15-2000

PA. 345 1990, APPROVED BY LIVINGSTON COUNTY

Surveyor's Michigan License No. 35999

PRICE GROUP ON 2-2-2000 CO REF JED

