

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

LIVINGSTON Located In: Corner Code #  
(County)  
1. Public Land Survey T 1 N 4 E G-06  
T    R     
T    R     
T    R     
2. Property Controlling S    T    R     
in Section S    T    R     
3. Miscellaneous S    T    R     
Property in Sec. S    T    R   

2000 SEP 28 10 18

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

LSC #1280m  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I JACK K. SMITH, in a field survey on AUGUST 25, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 JOSEPH WAMPLER SET POST  
BLACK OAK 11" S72 1/2°W 27.72'  
WHITE OAK 5" S525°E 74.58'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A 1/2" REROD 1/2 FOOT BELOW THE SURFACE OF THE GRAVEL AND 3 FEET WEST OF THE CENTERLINE OF BENTLEY LAKE ROAD. THERE IS NO OCCUPATION EAST OR WEST. DISTANCES TO THE NORTH, SOUTH, EAST AND WEST COMPARE WELL.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-06 EAST 1/4 CORNER SECTION 16, T1N, R4E, PUTNAM TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  
SET 1 1/4" x 36" BREAK OFF STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED  
SURVEYOR #35999 IN PLACE OF 1/2" REROD

SOUTH	1/2" REROD IRON MARKING SPEARS ROAD INTERSECTION	23.30'
N80°E	SW CORNER OF GARAGE FOUNDATION- HOUSE # 8485	113.12'
S35°E	SPIKE AND REMON TAG ON WEST SIDE OF DOUBLE 8" HICKORY	85.80'
S50°W	SPIKE AND REMON TAG ON NORTH SIDE OF 18" OAK	95.90'
N40°W	SPIKE AND REMON TAG ON WEST SIDE OF 1999 UTILITY POLE	52.08'

Signed by [Signature] Date 9-15-2000  
P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY  
Surveyor's Michigan License No. 35999 GROUP ON 2-2-2000 CO. REP LED

