

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>9</u> T. <u>1</u> N. <u>5</u> E. <u>X</u>		E-3, F-3, E-4
2. PROPERTY CONTROLLING IN SECTION <u>9</u> T. <u>1</u> N. <u>5</u> E. <u>X</u>		<u>1</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. _____ E. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on April, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- | | |
|--|--|
| F-3 Replaced from old witness and tie to the creek | E-3 Recovered 3/8" iron rod in fence corner. Corner witnessed by Boss Surveying, Howell, Michigan. |
| 1 Set 1" iron pipe on line and equal distance from government corners east and west. | E-4 Recovered 1" iron rod. Placed 1" iron pipe with plastic cap over it. Recovered with witness from Munsel & Garlock, surveyors in Howell, Michigan |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|---------------------------------------|--|
| F-3 1" iron pipe with plastic cap | E-3 Found 3/8" rod in fence corner, placed plastic cap on it |
| S.35°E. 30.05' 16" apple, PK & tag | N.69°W. 6.90' 20" white oak, PK |
| S.56°E. 157.08' 32" hickory, PK & tag | North 35.16' 18" black oak, PK |
| N.64°E. 18.53' 8" cherry, PK & tag | N.22°E. 14.50' 8" ash, PK |
| N.14°E. 45.89' 16" walnut, PK & tag | S.30°W. 98.48' 8" black oak, PK |
| 1 1" iron pipe with plastic cap | E-4 1" iron pipe with plastic cap |
| S.82°E. 6.34' 18" white oak, PK | S.80°E. 40.74' 44" black oak, PK |
| N.18°W. 9.62' 20" white oak, PK | S.20°E. 11.39' 14" maple, PK |
| N.66°W. 38.30' 8" black oak, PK | S.01°W. 31.95' 15" white oak, PK |
| S.74°W. 2.92' fence corner post | S.65°E. 64.75' Nash headstone, SW corner, base |

SIGNED BY Donald L. Bissell DATE April 13, 1977 /stone

SURVEYOR'S MICHIGAN REGISTRATION NO. 18655 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Donald L. Bissell DATE April 13, 1977
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 18655