

SURVEY &  
REMONUMENTATION

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in  
LIVINGSTON

(County)

Located in: Hamburg

Corner Code #

1. Public Land Survey T 1N R 5E E6  
T R  
T R  
T R
2. Property Controlling S T R  
in Section S T R
3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

2000 OCT 19 A 10: 32

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

LSC #1313m

Register of Deeds Stamp and File Number

I, Bryan L. Boss, in a field survey on MAY 30, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

SET POST  
ASPEN 16" N30°E 1.24 CH.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON ROD INSIDE A PIPE CONCRETE  
MONUMENT IN CREEK.  
ALSO FOUND A 1/2" IRON PIPE WITH CAP #15411 1.34. SOUTH

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET BRASS CAP STAMPED "LIVINGSTON  
COUNTY REMONUMENTATION CORNER" ON TOP  
OF THE EXISTING CONCRETE MONUMENT  
NORTH 52.48' SET REMON NAIL/TAG E/SIDE P.  
POLE  
S60°E 73.17' SET REMON NAIL/TAG S/SIDE DEAD  
ELM  
S30°W 49.80' SET REMON NAIL/TAG W/SIDE 4" ELM

N60°W 53.90' SET REMON NAIL/TAG S/SIDE TWIN  
OAK  
SOUTH 1.34' FOUND PIPE WITH CAP #15411

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5			4		3		2		1	
3												
4	7	8			9		10		11		12	
5												
6	18	17			16		15		14		13	
7												
8	19	20			21		22		23		24	
9												
10	30	29			28		27		26		25	
11												
12	31	32			33		34		35		36	
13												



P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 4-5-2000 CO. REP JED

Signed by *Bryan L. Boss*

Date Sept. 5, 2000

Surveyor's Michigan License No. 29238