

SURVEY &  
REMONUMENTATION

DEC 13 1993

COMMISSION

For corners in

Livingston

(County)

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Located In:

Corner Code ##

1. Public Land Survey

T 2N R 4E

J-13

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

NOV 29 3 37 PM '93  
NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI  
48843

RECORDED  
FILED

L.S.C. #49m

Register of Deeds Stamp & File Number

I, Darrell D Hughes, in a field survey on October 22, 19 93,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO survey notes: April 15, 1825  
GLO witnesses: WO 12-S27W-.16 ch.  
WO 17-N84E-1.66 ch.

Additional historical data on rear of sheet:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
Found  $\frac{1}{2}$ " I Rod in center of Schafer Rd. flush with Asphalt surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-13: S  $\frac{1}{4}$  cor. Section 35 T2N-R4E, reset with  $1\frac{1}{4}$ " X 36" breakaway I. Pipe with Liv. Co.  
brass cap on top and in a Mon. Box.  
S20W-76.20'-sp W/s 6" Walnut  
N80W-178.87'-sp S/s 36" W Oak  
North-25.44'-sp E/s wood cor. post  
North-49.35'-sp E/s U Pole  
N55W-166.98'-SE cor. Garage of brick  
North-1.7' $\pm$ -ctr. Schafer Rd  
East-27.42'-N  $\frac{1}{4}$  cor. Sec. 2 T1N-R4E

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

Surveyor's Michigan License No. 19834

Approved by Liv. Co. Peer Group: Oct. 30, 1993

Date

11-29-93

October 23, 1993

J-13: S 1/4 Cor. Sec. 35 Marion Twp. Liv. Co. MI

Found  $\frac{1}{2}$ " iron rod in center line of Schafer Rd. and level with surface of asphalt with old fence line to the North. Earliest known witness is by M.W. Bullock, Co. Surveyor, 1880, with measure to SW Cor. of 40.11 ch. (2647.26') and measures today 2646.19' on relatively flat ground. Act 74's filed by Garlock 1971 and A.F. Miller 1977. The following known surveyors have used this Corner: D. Hughes, A.F. Miller, P.L. Benton, Boss Engineering, L.W. Munsell and C.E. Garlock. Sweep of area found no additional irons. One tree to the West and SSE; balance of area open. Road surface is asphalt.