

SURVEY &
REMONUMENTATION

FEB 26 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

SECTION

For corners in

LIVINGSTON
(County)

Located in:

Corner Code #

2000 NOV -8 A 9:43

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC #1347 m

9/ Register of Deeds Stamp & File Number

1. Public Land Survey T 2 N R 4 E E-09
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, JACK K SMITH, in a field survey on OCT. 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4				2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SIBLEY SET POST
BLACK OAK 8" S14°W 40.92'
BLACK OAK 7" N6 1/2°W 36.96'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

WE FOUND MULTIPLE CORNER LOCATIONS MONUMENTED AT E-09. THERE IS A 2" STEEL PIPE STANDING APPROXIMATELY 2 FEET ABOVE THE SURROUNDING GROUND AND A 1/2" REROD THAT IS APPROXIMATELY 0.5 FEET TO THE WEST. THE 2" STEEL PIPE WAS USED BY MUNSELL IN 1958 AND WAS ACCEPTED AS THE BEST PERPETUATION OF E-09. THERE ARE FENCE LINES AND TREE ROWS TO THE SOUTH, EAST AND WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-09 SOUTHWEST CORNER SECTION 21, T2N, R4E, MARION TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
CORNER IS THE FOUND 2" STEEL PIPE WITH A LIVINGSTON COUNTY REMONUMENTATION BRASS CAP WITH SURVEYOR #35999 CEMENTED IN.

SOUTH SPIKE AND LIVINGSTON COUNTY REMON TAG IN WEST SIDE OF A 30" OAK 2.47'
S80°E SPIKE AND LIVINGSTON COUNTY REMON TAG IN NORTH SIDE OF A 30" OAK 21.16'
S20°W SPIKE AND LIVINGSTON COUNTY REMON TAG IN WEST SIDE OF A 6" OAK 42.58'
WEST 1/2" REROD 0.56'
S50°W SPIKE AND LIVINGSTON COUNTY REMON TAG IN NW SIDE OF A 10" OAK 59.32'

Signed by

Date

Surveyor's Michigan License No. 35999

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

PEER GROUP ON 9-6-2000 CO. REP JED

