SURVEY & REMONUMENTA

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 **FILED**

2000 NOV 291A 9:50

For corners in	_ Located in: GENOA	Corner Code #	9	NA NA	NCY HA	VIIAN	יי ח
(County)	_ Located III. OLNON	0011101 0000 11		REG	iisten n	ום חודבו	ñe
1. Public Land Survey	T <u>2N</u> R <u>5E</u> T R	F-7	,	. C1 A 1146	STON C 4884	13	G MI.
2. Property Controlling	T R T R S T R			L	SC #13	89m	
in Section	SR						
Miscellaneous Property in Sec.	S T R S T R		Register of	Deeds Stan	np and F	ile Nun	nber
4. Lot No , Rec	corded Plat						
5. Private Claims				A B C P	# F G	+++	1 1
			2		+i+	-;-+	-i-+
	•		3		111		
Bryan L. Boss	n a field survey on	FEBRUARY 28, 2000			†††	- 10	-' 🕇
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the			ts mentioned 5				11
current manual of survey instru	uctions of the United States De	epartment of the Interior, Bu	reau of Land	18	16	— 15 ——	- 14 T
Management or by a decree of a	Court of Law and/or that the o	corner points mentioned in lir	nes 3,4 and b /		1-9-1	\neg	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.		a Decree of a 8	19-120-	+21+	-22 	- 23	
		e-monumented, recovered,	loullu as 9		+++		_
NOTE: Not more than 4 cor	mers, all in the same town ar	nd range, may be recorder	d 10	30-29	1 28 1		- 26 - -
on this certificate.		,					11
			12	31 - 32	1-33-	34-	-35
A. Description of original m	onument and accessories and	d/or subsequent restoration	on:	\ <u></u>	ااا		
1823 BY S. SIBLEY, DEPU	TY SURVEYOR						
SET POST	uze	٠.					
W. OAK 10" N 10° E 74 LIN B. OAK 9" S 10 1/2" W 15 L		•					
* ·		•					
B. Description of corner evi	idence found and/or method S SOUTHWESTERLY +/- 6' SOU	applied in restoring or ree TH OF	stablishing corr	ner:			
CENTER LINE CROOKED							

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

AND A BRASS CAP STAMPED "LIVINGSTON COUNTY REMONUMENTATION CORNER". NORTH 32.89' FOUND 1/2" IRON N 25° E 38.00' SET REMON NAIL/TAIL SE/SIDE 18" S 30° E 39,21' SET REMON NAIL/TAG SW/SIDE 12" COTTONWOOD S 45° W 22.50' SET REMON NAIL/TAG NW/SIDE 24" OAK

SET 1 1/4" X 30" PIPE WITH 6" BREAKAWAY PIPE

N 45° W 57.65' SET REMON NAIL/TAG S/SIDE 6"

29238 LAND

OF MICHIG

BRYAN L BOSS and Surveyor NO.

29238