

**SURVEY & REMONUMENTATION**

FEB 25 1999

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

**FILED**

For corners in

LIVINGSTON  
(County)

Located In:

Corner Code #

- |                                    |                         |           |
|------------------------------------|-------------------------|-----------|
| 1. Public Land Survey              | T <u>3N</u> R <u>3E</u> | <u>I7</u> |
|                                    | T___ R___               | _____     |
|                                    | T___ R___               | _____     |
|                                    | T___ R___               | _____     |
| 2. Property Controlling in Section | S___ T___ R___          | _____     |
|                                    | S___ T___ R___          | _____     |
| 3. Miscellaneous Property in Sec.  | S___ T___ R___          | _____     |
|                                    | S___ T___ R___          | _____     |

91

1998 AUG 20 P 4:44

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

L.S.C. #871m

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, CHARLES E. GARLOCK, in a field survey on AUG. 7, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

- A. Description of original monument and accessories and/or subsequent restoration:  
GLO SURVEY DATED: APRIL 15, 1825 BY S. SIBLEY, DS  
GLO WITNESSES: MAPLE 13-S53E-10 LKS  
MAPLE 12-N59W-17 LKS



ADDITIONAL DATA ON REAR OF SHEET

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A SQUARE HEADED BOLT IN A MON. BOX ON CENTERLINE OF FOWLerville ROAD AND CENTER-LINE OF ROAD TO THE WEST AND OCCUPATION TO THE EAST.   
 3' SOUTH TO AND CENTER-  
 ^

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I7: NW COR. SEC. 23 T3N-R3E, HANDY TWP. LIV. CO. MI, REPLACED BOLT WITH 1 1/4" X 36" BREAK-AWAY I. PIPE WITH LIV. REMON. BRASS CAP ON TOP.  
N85W-132.52'-SP & TAG S/S DBL 12" ELM  
N15E-138.18'-SP & TAG W/S 20" BOX ELDER  
N50E-31.61'-SP & TAG N/S 8" ELM  
N60E-99.82'-SP 7 TAG S/S 18' MAPLE  
ON CTR. OF FOWLerville RD AND SOUTH 3' TO CTR OF VAN BUREN RD.

Signed by Charles E. Garlock  
Surveyor's Michigan License No. 14762

Date AUGUST 8, 1998