

# SURVEY & REMONUMENTATION

FEB 26 2001

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

2000 OCT 30 A 9:22

LIVINGSTON Located In: Corner Code #  
(County)  
1. Public Land Survey T 3 N R 3 E D-03  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

LSC #1338m  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, JACK K. SMITH, in a field survey on OCTOBER 11, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4		3		2		1
3				8								
4		7				9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SYLVESTER SIBLEY SET POST  
MAPLE 26" N24°E 17.16'  
WHITE ASH 8" S61 1/2°E 19.8'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A 3/4" ID PIPE WITH MARY BARNWELL'S CAP IN A STONE PILE NEAR THE INTERSECTION OF TREE LINES AND FENCE LINES EAST, WEST AND SOUTH.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-03 NORTH 1/4 CORNER SECTION 8, T3N, R3E, HANDY TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  
SET 1 1/4" x 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED SURVEYOR #35999  
PLACE OF THE 3/4" PIPE THAT CURRENTLY MARKS THE CORNER.

NORTH SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 4" OAK 3.42'  
N85°E SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 6" ELM 11.92'  
EAST SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 14" HICKORY 25.85'  
S10°E SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 6" MAPLE 15.11'  
S10°E SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 12" ASH (1 of 7) 26.95'

Signed by

Date

10-16-2000

Surveyor's Michigan License No. 35999

