

SURVEY &
REMONUMENTATION

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>LIVINGSTON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	<u>T 3 N R 3 E</u>	<u>E-04</u>
	<u>T</u> <u>R</u>	
	<u>T</u> <u>R</u>	
	<u>T</u> <u>R</u>	
2. Property Controlling in Section	<u>S</u> <u>T</u> <u>R</u>	
	<u>S</u> <u>T</u> <u>R</u>	
3. Miscellaneous Property in Sec.	<u>S</u> <u>T</u> <u>R</u>	
	<u>S</u> <u>T</u> <u>R</u>	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, JACK K. SMITH, in a field survey on OCTOBER 11, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SYLVESTER SIBLEY SET POST
BLACK ASH 7" S40°W 15.18'
BLACK ASH 7" N13°W 2.64'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A 1" SQUARE BAR 1' WEST OF THE CENTER LINE OF NICHOLSON ROAD. THERE IS LIGHT OCCUPATION TO THE EAST AND WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
E-04 WEST 1/4 CORNER SECTION 9, T3N, R3E, HANDY TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
SET 1 1/4" x 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED SURVEYOR #35999
IN A MONUMENT BOX IN PLACE OF THE 1" SQUARE BAR THAT CURRENTLY MARKS THE CORNER.

N70°W	SPIKE AND LIV. CO. REMON TAG IN NORTH SIDE OF 12" ASH	28.56'
N10°W	SPIKE AND LIV. CO. REMON TAG IN NORTH SIDE OF 20" WALNUT	157.07'
S45°E	SPIKE AND LIV. CO. REMON TAG IN NORTH SIDE OF UTILITY POLE	76.31'
WEST	SPIKE AND LIV. CO. REMON TAG IN NORTH SIDE OF 12" ASH	35.62'

Signed by [Signature] Date 10-16-2000

Surveyor's Michigan License No. 35999

2000 OCT 30 A 9:22

HANDY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48043

LSC #1341m

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

