

SURVEY & REMONUMENTATION

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

LIVINGSTON Located In: Corner Code #
(County)
1. Public Land Survey T3N R5E F-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

2000 AUG 29 A 9 31

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC #1269m
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, CHARLES E. GARLOCK, in a field survey on JULY 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1823 S. SIBLEY SET POST
WHITE OAK 10 N 54° E 17.82'
WHITE OAK 8 S 4 1/2° W 7.92'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 5/8" SQUARE BAR ON CENTERLINE OF NORTH-SOUTH ROAD AND 6' SOUTH OF THE CENTERLINE OF THE ROAD TO THE WEST AND ON LINE WITH THE REMAINS OF AN OLD FENCE LINE TO THE EAST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11 SOUTH 1/4 CORNER SECTION 28, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
SET 1 1/4" X 36" BREAKAWAY STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEYOR #14762 WHERE OLD IRON WAS FOUND.

S50°W SP&TAG N/S 18" PIGNUT HICKORY
N70°W SP&TAG S/S 20" HICKORY
N60°W SP&TAG S/S 15" HICKORY
S20°E SP&TAG E/S 16" OAK

50.37'
102.24'
60.68'
76.92'



Signed by Charles E. Garlock Date 7-21-00

Surveyor's Michigan License No. 14762

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975 REVISED JAN, 1983
REVISED OCT, 1995

PA. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 3-15-2000 CO. REP JED