

MACKINAC COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac
(County)

Located In:

Corner Code ##

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGIST. OF DEEDS

NOV 15 1996

AM PM
7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

1. Public Land Survey T 40N R 4W L-1
T R
T R 1/4 cor common to
T R Sec.'s 1 & 36
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, Neil E. Hill, in a field survey on SEPTEMBER 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. notes. Set 1/4 corner post.

8" Birch S20E 11 lks

10" Tamarack S85W 26 lks

From survey of Section 36 by C.A.&E. 1977.

1" sq. spike.

Recorded on U.S.F.S. Plat drawing.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rerod with cap #27447 in monument box in centerline of E-W blacktop road.

5" Cedar N17W 31.30'

PP N66E 42.35'

PP S65E 56.45'

4" Balsam S10W 24.30'

Accepted corner location

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 9-30-96

James H. Granger

Also recorded in: T 41N, R4W, L-13

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1/2" rerod with cap #27447 in monument box in E-W blacktop road centerline.

Property corner North 33'

18" Cedar N15E 39.64'

PP N70E 47.00'

6" Balsam S10E 39.94'

8" Spruce S40W 45.85'



Signed by Neil E. Hill R.S., P.C.

Date

SEPTEMBER 30, 1996

Surveyor's Michigan License No. 27447