

SURVEY & REMONUMENTATION

OCT 1 1994

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac

(County)

Located in:

Corner Code ##

1. Public Land Survey T 40N R 4W
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

MC C-1/D-1

MC C-13/D-13

#1

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGISTER OF DEEDS

SEP 6 1994

AM

PM

7/8/9/10/11/12/13/14/15/16

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Neil E. Hill, in a field survey on AUGUST 22, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set 3" Fir

Tie 10" Fir N22E 2.00 chains

Corner 22 chains West of 1/4 Corner (22.67 ch or 1496.15' today)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1978 MDOT tied this corner

1982 Bill Karr tied and used; recorded in Liber C, Page 061

1994 Found 2 1/4" Pipe 16" above ground and 4 existing witness trees 168 feet East of shore of Lake Michigan:

8" Spruce N81E 51.68' (gone)
4" Cedar S52E 2.85'

6" W. Pine S44W 14.40'
3" Tw. Cedar West 11.57'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted corner in its present location.

Removed 2 1/4" Pipe and replaced with 5/8" re-rod and 4" aluminum cap

6" W. Pine S44W 14.34' (MDOT tag)

4" Cedar S52E 2.88' (MDOT tag)

6" Spruce S20W 17.18"

3" Tw. Cedar Due West 11.34'

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 8-16-94

James H. Branger

Signed by Neil E. Hill P.S.

Date

August 22, 1994

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

D-0269

09-06-94 1CL3183

MISC