

**MACKINAC COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Mackinac (County) Located In: _____ Corner Code #/ # _____

1. Public Land Survey T 40N R 04W P.C.C. 18
 T _____ R _____ NW Cor. PC 18
 T _____ R _____
 T _____ R _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

#22

RECEIVED & FILED
 DIANE FRANKOVICH
 REGISTER OF DEEDS
 DEC 11 1995
 AM _____ PM _____
 7:18:54
 Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Neil E. Hill, in a field survey on NOVEMBER 17, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO notes. Set post
 6" Beech N71W 19 lks
 6" Sugar Maple S22E 28lks.

See sketch on reverse

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Corner found placed by Charlevoix Engineering & Abstract, Sept. 1975
 Accepted this location.

14" Spruce N75E 47.13'
 10" Spruce S43E 43.97'
 12" Poplar N80W 70.18'

ACCEPTED BY THE MACKINAC COUNTY SURVEY FIELD GROUP AS THE OFFICIAL CORNER UNDER P.A. 349 OF 1971 AT A MEETING HELD ON 9-10-95

James H. Granger



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1/2" pipe with cap. Replaced with 5/8" re-rod std. county remonumentation corner.
 P.Pole N20E 34.55' S09-04-01E 458.70 feet to SW Cor. PC 18
 8" Poplar N55E 34.58' N09-04-01W 1669.80 feet to NW Cor. PC 19
 3" Spruce N80E 29.05'
 6" Poplar S70E 36.73'

Signed by Neil E. Hill P.S. Date NOVEMBER 17, 1995
 Surveyor's Michigan License No. 27447

Sec. 10

99' 6 1/2 ft

Sec 15

T40 N, R. 4W

550' 0' claim

N 1/3 P.C. 19

550' 0' claim

M 1/3 P.C. 19

551' 0' claim

S 1/3 P.C. 19

458' 0' etc

P.C. 18

