## MACKINAC COUNTY REMONUMENTATION CORNER

## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requir	ement of Act 74, Mich. P.A.	1970
Mackinac (County)	Located In:	Corner Code ##	RECEIVED 8 FILED
<ol> <li>Public Land Survey</li> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T <u>YOU</u> ROYW T R T R T R S T R S T R S T R S T R S T R S T R	P.C.C. 19 Between M 1/3 & N 1/3 PC 19	DEC 1 1 1995  AM PM 718  Start From 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
4. Lot No.	Recorded Plat		— ABCDEFGHIJKIM
do hereby certify that under rein fines 1 and 2 above were current manual of survey inst Management or by a decree o above were in conformance w Court of Law; established, expressed below:  NOTE: Not more than 4 on this certificate	monument and accessories an	of 1970, the corner points mentione not rules therefore as required in the timent of the Interior, Bureau of Langr points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found a not range, may be recorded	d e 6 18 17 16 15 14 13 d 7 d 7 d 7 d 7 d 7 d 7 d 7 d 7 d 7 d
1" pipe set by Charle	evidence found and/or method avoix Engineering & Abstract		shing corner:
Distance checks with Accepted corner locat 9" Balsam So 14" Cedar N2 6" Balsam N3	ion. uth 1.43' 25W 18.50'	ACCEPTED BY THE MACKINAC SURVEY PEFFI LEGAL AS THE OFFISIAL CORMER UNIGER PA 845 OF 1980 AT A MEETING HELLOW 9-18-95 James H. LL	COUNTY BUTTON NO. 27447
Found 3/4" pipe, 36" l 12" Tw. Maple 3" Cedar 6" Maple	ent for corner and accessories of long. Replaced with 5/8" re S40W 9.53' S20W 9.07' N70W 12.65' N35W 11.70'	-rod std. county remonumer S09-04-01E 1113	