

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Mackinac Co.

3 Corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. _____ N. _____ S., R. _____ E. _____ W. _____	
2. PROPERTY CONTROLLING IN SECTION	5, T. 41 N. 11 E. _____ S., R. _____ E. _____ W. _____	1, 2, 7
3. MISCELLANEOUS PROPERTY IN SECTION	_____, T. _____ N. _____ S., R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David E. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-29, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

West 1/16 cor. on the north sec. line of sec. 5. Not prev. est.

East 1/16 cor. on the north sec. line of sec. 5. Not prev. est.

North 1/16 cor. on the east side of sec. 5. Not prev. est.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Set M.P.O.L. between the NW sec. cor. and the North 1/4 cor. of sec. 5.

Set M.P.O.L. between the North 1/4 cor. and the NE sec. cor. of sec. 5.

Set M.P.O.L. between the N.E. Sec. Cor. and the E $\frac{1}{4}$ cor. of sec. 5. G.L.O. record is 40 chs. for the $\frac{1}{2}$ mile.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" pipe with Plastic R.L.S. cap. Bearings: 14" Spruce, S17°E, 27.4' & 10" R. Maple, N52°E, 49.4' & 10" Hemlock, N22°W, 28.2' & 6" Spruce, S29°W, 52.2'. Corner is buried in center line of E-W road.

1" pipe with plastic R.L.S. cap. Bearings: 8" R. Maple, S50°W, 45.1' & 8" Beech, S5°W, 38.3' & 8" H. Maple, S44°E, 57.3' & 6" H. Maple, N65°E, 58.1'. Corner buried in center line of E-W road.

1" pipe with plastic R.L.S. cap. Bearings: 5" H. Maple, S53°E, 34.45' & 8" R. Maple, N41°E, 58.6' & 8" W. Pine, N25°W, 96.55' & 10" W. Birch, S87°W, 34.4'. Corner is buried in blacktop, 1.0' West of center line.

SIGNED BY

David E. Babbitt

DATE 8-3-82

David E. Babbitt
SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES: