

MAR 13 1998

SECTION

MACKINAC COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac
(County)

Located In:

Corner Code ##

1. Public Land Survey T 41N R 3W B-9
T _____ R _____ 1/4 Cor common
T _____ R _____ to Sec's 19 & 30
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Neil E. Hill

DECEMBER 22 97

I, Neil E. Hill, in a field survey on DECEMBER 22 97, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- | | | | | | |
|------|--|--------------|----------|-----------|--------|
| 1845 | GLO notes | William Burt | 4" Aspen | S46W | 7 lks |
| | | | 8" Beech | N50 1/2 E | 23 lks |
| 1980 | L. Feindt set 1/4" pipe at fence intersection West & South | | | | |
| | Recorded Liber B, page 176 | | | | |


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- 1997 Found 3/4" pipe (Old witnesses)
- | | | |
|-------------|------|---------------|
| 7" Tamarack | S55E | 48.07' (gone) |
| 7" Cedar | N25E | 5.02' |
| 6" Cedar | N66W | 6.65' |
| 16" W. Pine | S60W | 74.10' |
- Accepted corner location.

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 12-12-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1997 Found 3/4" pipe - placed 1/2" rerod with remonumentation cap inside found pipe.
- | | | |
|-------------|------|--------|
| 10" Cedar | N25E | 4.99' |
| 10" Cedar | N66W | 6.60' |
| 20" W. Pine | S60W | 74.10' |
| 8" Cedar | S25W | 18.10' |
| 4" Birch | S15E | 29.22' |



Signed by Neil E. Hill P.S.
Surveyor's Michigan License No. 27447

Date DECEMBER 22, 1997