## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Mackinac	_ Located In:	Corner Code #			
(County)					
1. Public Land Survey	T R				
2. Property Controlling in Section	S 14 T 42N R 1E S 14 T 42N R 1E S T R	10 11			
3. Miscellaneous	s T R				
Property in Sec.	s r R				
•			Regist	er of Deeds S	Stamp & File Number
4. Lot No. , Re	corded Plat		A B (	DEF	GHIJKLM
5. Private Claims	<u> </u>		1		
	10 02/	11/2010	2 6	<del>┠─</del> ┡─ <del>┠</del> ─┡	
. Stophon I Sweetenski :	n a field survey on 11 02/0	08/2010 do hereby state	3	<del>                                     </del>	<del>- - - - - - -</del>
ı, <u>Stephan J. Szyszkoski</u> , i		·	╮ <b>4 ├</b> ─ ? ──	<del>├</del> ── ╞──├── ⋟	)101112
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2					
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6					
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7					
	rd of Land Surveyors or by a Decree				1 22 23 24
re-established, monumented, recov		<b></b>	1 1		
re established, monumented, recov	C.C.C., 104.114 42 5747 33332 2333		9		
			10 30	29-1-26	8 27 26 25
NOTE: Not more than 2 corr	ners, all in the same town and range	e, may be recorded	11	╂═╂═╂	
on this certificate.			12-31-	32 3:	3 34 35 36
			13		<u>L_L_L_L_L_L_</u>
A. Description of original monument and accessories and/or subsequent restoration:					

- (10-Sec. 14) South 1/16 corner between Sections 14 and 15. Not established in the original survey.
- (11-Sec. 14) Southwest 1/16 corner, Section 14. Not established in the original survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (10-Sec. 14) Established the corner midway and on the Section line between Section corner 1312.74' south and Quarter corner 1312.74' north.
- (11-Sec. 14) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. (10) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 7" Balsam S42W 31.8' mrkd "SW1/16 BT" 6" Cedar N77W 12.6' mrkd "S1/16 BT" 6" W.Birch S89W 23.7' do 10" Cedar N17W 18.15' do 9" Cedar N14E 49.4' do 10" Cedar N45E 6.6' do 10" W.Birch S50E 2.05' do 8" Cedar South 14.7' do Bearings are magnetic. Bearings are magnetic.

Surveyor's Michigan License No.

05/20/2010

SZYSZKOSK LAND

STEPHAN

SURVEYOR

MAND. SV

For the Michigan Department of Natural Resources and Environment, Forest Manageme

33986

47357

sed Jan., 1983

47358

Rervised Oct., 1995