

MAR 20 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in

Mackinac County Located in: Corner Code #

1. Public Land Survey T42N R01W WCMC G/H-11
T R
T R
T R #004

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGISTER OF DEEDS

FEB 25 2000

AM PM
7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Neil E. Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes J Mullett 8" Birch N 17 W 35 lks

1953 C E Smith
Recorded the "Roach Plat", shows corner location, no witnesses listed

1965 T L Jackson 8" Cedar N 40 E 9.75'
Was ordered by a 6" Cedar S 80 E 24.45'
Circuit Court Decree File No 1949 dated Nov 1961
Recorded Liber 173 Page 439, to reset the corner location
Notes large dolomite boulder adjacent to corner location
Book 1 Page 314

1981 Sherman Chamerlain - Charleviox A & E
Shows location of corner on survey for Jack Law
No witnesses listed

No Subsequent Information

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-05-99
Neil E. Hill

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


1999 Fd no evidence of original or subsequent corners
Large dolomite boulder has been pushed into lake
Fd witness nail N 40 E in base of cedar, approx 2' under sand, and found other witness nail S 80 E
Reset corner from witness nails
Set 1/2 rod with 4" Alum. remonumentation cap

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" rod with 4" Alum. remonumentation cap
Corner is in a marsh area

10" Cedar N 40 E 9.75'
8" Cedar S 80 E 24.45'
Pipe in Conc N 35 W 52.24'
Pipe N 50 W 122.67'

Bearings are compass bearings, corrected for declination, all distances are to a double- head nail in the side of the witness object unless otherwise noted.



Signed by Neil E. Hill P.S.L.C.

Date January 21 2000

Surveyor's Michigan License No. 27447