

## MAR 2 0 2000

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

## **Mackinac County Remonumentation Corner**

For corners in

Mackinac County

Located in:

Corner Code #

1. Public Land Survey

| T41N | R01V |
|------|------|
| T    | R    |
| Т    | R    |
| Т    | R    |
| T    | R    |
| Т    | R    |

R01W

WCMC K/L - 13 / WCMC K/L - 1

2. Property Controlling in Section

Miscellaneous Property in Sec. S S R #009

DIANE FRANKOVICH MACKINAC COUNTY REGISTED OF DEEDS

FEB 2 5 2000

AM

718 911

2 3

6

7

8

9 10

11

12 13 30

MR 2]]][2]3] /[5] ( of Deeds Stamp & File Number

27

L

4. Lot No.

, Recorded Plat

5. Private Claims

I, Neil E. Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes A Burt

6" Spruce 8" Aspen

S 63 E Due N

1.80 Ch 3.73 Ch ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A.

**3**45 OF 1990 AT A MEETING HELD ON 11-05-9

No Subsequent Information

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999 Fd poured concrete monument with 1/2" pipe Accepted corner location Placed 4" Alum. remonumentation cap

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Corner is a 1/2" pipe in a poured concrete monument with 4" Alum, remonumentation cast Corner is along gravel driveway

18" Cedar

N 60 E N 05 W

8" Cedar 18" Pine

S 55 W

58.73

Cabin S 15 W 21.54 17.61'

(NE corner block foundation)

MEIL E 

Land

Surveyor

No.

Bearings are compass bearings, corrected for declination, all distances are to a double- head nail in the side of the witness object unless otherwise noted.

Date

ill 85. P.C. Signed by

January 21 2000

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995 C0005