

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Mackinac Co.

3 Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>42</u> N. <u>3</u> R. <u>6</u> E. <u>W.</u>		A-4, B-3, L-9
2. PROPERTY CONTROLL- ING IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-23 & 5-8, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- A-4 Quarter Corner bet. Sec. 7, T42N R6W and Sec. 12, T42N R7W.
- B-3 Quarter Corner bet. Sec's. 6-7, set by D.C. DeLaMater, R.L.S., 1-17-51.
- L-9 Quarter Corner bet. Sec's. 24-25, set by H. Brevoort, Jr., D.S. in 1845.
Record: A Birch 12" for quarter corner.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-4 Re-witnesses corner as set by myself in 12-14-63. Found 12" Soft Maple witness, N32°W, 58 lks. marked 12-14-63, has been cut. Found 10" H. Maple, S24°W, 39½ lks., marked 12-14-63 still green and in good condition.
- B-3 Found original Beech witness, N2°W, 36 lks, now a dead stub, 8' high. Original maple witness is still green. Found 12" Maple, S73°E, 7 lks. marked 1951 is now 14" green, marks grown over. Found 12" Beech, S8°W, 23 lks., marked 1951, now dead. Found 16" W. Pine, N67°W, 49 lks, marked 1951 is now 24" DBH, marks completely grown over.
- L-9 Restored cor. 0.8' West of original Y. Birch Cor. tree.(green). Has been chopped out and grown over. Verified age by annual ring count.
- A-4 1" pipe with 4" Brass cap at corner. New Bearings: 18" H. Maple, N72°E, 41.1' & 12" Beech, N50°W, 49.2'.
- B-3 1" pipe with 4" Brass cap. New Bearings: 13" S. Maple, S5°E, 43.0' & 9" W. Pine, N7°E, 32.3'.
- L-9 Placed 1" pipe with 4" aluminum cap, 0.8' West of Corner. New Bearings: 7" Hemlock, S38°E, 8.8' & 10" Hemlock, N62°W, 51.8' & 10" R. Maple, N21°E, 40.0'. Corner lies 6.0' South of an E-W Hiking Trail.

SIGNED BY _____ DATE 10-9-80

Billy D. Buckler
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

