

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR. 10 - 11 West

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 6 - 1

DESCRIPTION OF CORNER MONUMENT 1 1/4" iron pipe

WITNESSES TO CORNER 7" cedar S 33°, W 44 links. Marked "CONDT"

9" cedar S 36°, W 56 links. Marked "LNEP"

2-24-58

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Re-witnessed corner as set by unknown surveyor. Found probable cedar bearing tree, bearing "44", W 14 links. Old scars on down cedar - badly rotted. 1/4 corner lies in N-S Fence line. Found by forestry division survey crew.

SURVEYORS SEAL

SIGNED *Billy D. Buckler*
REGISTERED LAND SURVEYOR DATE 6-18-59