

1994 Mackinac County Remonumentation Corner.

SURVEY &  
REMONUMENTATION  
COMMISSION  
APR 10 1995  
Mackinac County

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corner in

Mackinac County

Located In:

Corner Code #

1. Public Land Survey

T 42N R 4W

D-13

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED  
DAVID B. GUTHRIE  
LAND SURVEYOR  
NOV 09 1994

AM PM  
7:18 PM

Register of Deeds Stamp & File Number

I, David B. Guthrie on a field survey on April 20, 19 94,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1840: Established by Wm. Burt, G.L.O. Survey. Set Post and referenced:  
Sugar 12/N25E/41 Beech 10/N62W/35  
1980: Survey by Orlando Doyle. Set 3/4" Iron Bar  
1982: Survey by Lawrence Feindt. Set Corner.  
1988: Survey by James Granger. 3/4" Iron Bar.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found 3/4" Iron Rod in Monument Box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: Set Mackinac County Remonumentation Corner.  
A 5/8" by 24" Iron Rod with a 3" aluminum cap stamped to identify the  
corner set within a monument box.

Referenced:

S09°W - 34.38 feet - Utility Pole (Exist.)

S39°E - 60.87 feet - Stop Sign (Exist.)

N54°E - 86.22 feet - S.W. Cor. Church (Exist.)

N20°W - 51.69 feet - Stop Sign (Exist.)

East - 30.37 feet - 3/4" Iron Rod in Monument Box

Signed by

*David B. Guthrie*

Date

*Oct. 21, 1994*

Surveyor's Michigan License No.

22435

11-09-94

D-0323

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

REVISED MAY 14, 197

REVISED JAN., 198

