SURVEY & REMONUMENTATION

JAN 2 1 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Mackinac County Remonumentation Corner

Mackinac County	Located	in:		Corner Code #
1. Public Land Survey		T43N T T T	R01W R R R	L-11
	S S	T T	R R	
3. Miscellaneous	S S	T T	R R	

DIANE FRANKOVICH
MAKINAC COUNTY REDISTRACT OF DEEDS

DEC 3 1 1998

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat


5. Private Claims

I, Neil E Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes William A Burt	10" R Oak 12" Sugar	N 30 W S 11 W	28 lks 27 lks
1984 Harry Goodwin Fd Co	n Monument	Liber 3, Pag	je 244
1992 Stanly Kass Fd Concrete Monument Liber D, Page 160	12" Twin Oak 8" Aspen 16" Aspen Cable Marker	S 58 W N 17 W N 64 W S 54 E	56.27 ft 42.89 ft 55.18 ft 57.20 ft



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON 12-04-98 NEH

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998 Fd Conc Monument and 4 witnesses Accepted Corner location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a ½ re-bar in a concrete monument in a E-W road

12" Twin Oak	S 58 W	56.33'
8" Aspen	N 10 W	42.82'
16" Aspen	N 55 W	55.22'
14" W Pine	S 45 F	66 61'



Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

signed by Neil E Will P.S.

Date 12-29-99

Surveyor's Michigan License No. 27447