

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 5-6 W


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 7, 18, 12, 13

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 6/20/61

WITNESSES TO CORNER... 9" Balsam (S 18 NBT) S 1° E 72½ Links



Scribed Pine Stumps noted by Schaaf

24" W. Pine Stump (S 34° W) 80 Links

AND

26" W. Pine Stump S 14° W 78 Links

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Registered Land Surveyor. Found 2" Iron Pipe in place and two W. Pine Stumps which were noted as new bearings by Schaaf. Corner lies on South edge of road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 26, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler