

FEB 1 8 1994

Andrew Commence

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

| For corners  | s in                  | Filing Requi                      | rement of Act 74, Mich. P.A.  | 1970  |
|--|-----------------------|-----------------------------------|---|---|
|  | Mackinac              |                                   |   |   |
|  | (County)              | Located In:                       | Corner Code ++  | _ = 48 P ()   |
|  | ,,                    |                                   |   |   |
| 1. Public  | Land Survey           | T _43NR5W                         | F-1   | Divine the Kungon   |
|  | ·                     | T R                               |   | MACO  |
|  |                       | T FI                              |   |   |
|  |                       | T R                               |   | DEC 0 / 1989  |
| 2. Proper  | ty Controlling        | S T R                             |   | AM  |
| in Sect  |                       | S T R                             |   | 71813122222241213121516   |
| 3. Miscel  | laneous               | S T R                             |   | Register of Deeds Stamp & File Number                           |
| Proper   | ty in Sec.            | S T R                             |   |   |
|  |                       |                                   |   |   |
| 4. Lot No  | o , R                 | ecorded Plat                      |   | A B C D E F G H I J K L M                                       |
| 5. Private   | Claims                |                                   |   |   |
|  |                       |                                   |   | 2 6 5 4 4 7 3 7 7 7 7 7   |
|  |                       |                                   |   | 3   |
| Ne.  | il E. Hill            |                                   | October 1 93  | 4 - 7 - 8 9 10 11 12-   |
| l,   | ,                     | in a field survey on              | , 19  |   |
| do hereby c  | ertify that under req | uirements of P.A. 74, Michigan P. | A. of 1970, the corner points mentione<br>and rules therefore as required in th | 6 18 17 16 15 14 13   |
| current mar  | nd 2 above were in    | ctions of the United States Den   | artment of the Interior Bureau of Lan   | d 7   |
| current manual of survey instructions of the United States Department of the Interior, Bureau of Land  Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 |                       |                                   |   |   |
| above were   | in conformance wit    | h the rules of the Michigan Boar  | d of Land Surveyors or by a Decree of   | a   |
|  |                       | e-established, monumented, re     | e-monumented, recovered, found a  | AS 10 20 28 27 26 25  |
| expressed  |                       |                                   |   | 00 20 20 20 20 20   |
|  |                       | orners, all in the same town      | and range, may be recorded  | 11  |
| OI   | n this certificate.   |                                   |   | 12 31 32 33 34 35 36  |
|  |                       |                                   |   | 13  |
| A. Descri  |                       |                                   | nd/or subsequent restoration:   |   |
| 1845:  |                       |                                   |   | D.S., in the original G.L.O. survey                             |
|  |                       |                                   | , and established the fo  |   |
|  | 26" S. M              | aple N58E 44 link                 | .15   | 14" S. Maple - N28W 26 links                                    |
|  |                       |                                   |   |   |
| 1990: The USDA Forest Service found no other record of any subsequent corner restoration.  |                       |                                   |   |   |
|  |                       |                                   |   |   |
|  |                       |                                   |   |   |
|  |                       |                                   |   |   |
|  |                       |                                   |   |   |
| B. Descr   | iption of corner e    | vidence found and/or metho        | d applied in restoring or reestabli   | ishing corner:  |
| 1990:  | The HONA E            | mummer Commission Similar         | ing ogidinal ag anv (   | subsequent corner evidence. Corner                              |
| 17791  | nesision a            | se remetablished by               | compared the mean   | ortionate measured position between                             |
|  |                       |                                   | orthwest Corner of Sect:  |   |
|  | CHE MOT CHES          | se coffice and cus we             | T thomas t corner or sweet.   | THE LACTOR LACTOR INC.  |
| 1990:  | ACRIL GAT             | Format Sprving apt                | a 2 1/2" by 3 foot  | long pipe monument, with a 3 1/4"                               |
| ib 7 7 5;6  1  | diameter al           | uminum can, stammed               | to identify the corner  | rs monumented. Top of monument is                               |
|  | annenvinate           | ly 0.5 feet above                 | he oround. Establishe   | d the following references of which                             |
|  |                       |                                   | cribed, painted, and to   |   |
|  | 9" Mapl               | •                                 |   | 9" (Twin) Maple S21E 44.3 feet                                  |
|  | 12" Mapl              |                                   |   | Post w/sign N90E 2.6 feet                                       |
|  |                       |                                   |   | •   |
|  |                       |                                   |   | •   |
|  |                       |                                   |   | ;<br>;  |
| C. Descr   | iption of monume      | nt for corner and accessorie      | s established to perpetuate locat   | ting the position of the corner:                                |
| 1993:  | Found a 2             | 1/2" pipe monument,               | with a 3 1/4" diamete:  | r aluminum cap, stamped to identify                             |
|  |                       |                                   | fied 1990 witnesses.  |   |
|  |                       |                                   |   |   |
| Upon   | review, the           | location and withe                | esses for the corner a  | s recorded in Liber D-0128 (Corner                              |
| Record   | ls), are suff         | icient to perpetuate              | the corner location.  |   |
|  |                       |                                   |   |   |
|  |                       |                                   |   | ;*  |
|  |                       |                                   |   | <u></u>   |
|  |                       |                                   |   | tij<br>Ko   |
|  |                       |                                   |   | loa.  |
|  |                       |                                   |   | n Korija je   |
| Signed by No.D E Will PS. P.C. Date Land October 15 1993   |                       |                                   |   |   |
| Organica by  |                       |                                   |   |   |
| Surveyor's   | Michigan Licens       | e No27447                         | 34 <b>4</b> 73  | YOYOT FOR MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 |
| -  | _                     |                                   |   | AA7 REVISED MAY 14, 1975  |
|  |                       | Remonumentatio                    | n Surveyor  | REVISEO JAN., 1983  |
|  |                       |                                   |   | <b>夏</b> 君(*)   |