

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Mackinac COUNTY
T 43-44N R 8W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 3-4-33-34

CORNER MONUMENT 5/8" iron pin, driven in center of E-W road

DATE MONUMENT PLACED AND WITNESSED 4-10-69

WITNESSES TO CORNER..... 8" H. Maple (NBT) N24°E 66.7'



7" H. Maple (NBT) N10°W 54.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established according to County Road records and map made by D. A. Brotherton, 1916.

Corner lies in line with north edge of an old driveway to north.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-24-69
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing