

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43N N.R. 9W


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner common to sections 13-14-23-24

CORNER MONUMENT 1" pipe with 4" aluminum cap. (Buried)

DATE MONUMENT PLACED AND WITNESSED 7-18-62 with J. Halbach, D. F.

WITNESSES TO CORNER..... 6" Y. Birch (S14 NBT) N66°W, 82 links



6" Hard Maple (S24 NBT) S39°E 56 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established in intersection of fire lines in all four directions. Found no evidence of original corner but believe fire lines were located by Marcus Schaaf, Registered Land Surveyor.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 23, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler