

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 9 W


Mackinac COUNTY

DESCRIPTION OF CORNER M.C. for Sections 35-36

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/30/64 with Forestry Aide Burnis

WITNESSES TO CORNER..... 14" W. Pine, (M.C. NBT), N17°E, 28 lks.



10" W. Pine, (M.C. NBT), N 80° E, 105 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from down Wood Post and W. Pine, N 80° E, 105 lks., which is badly rotted, axe marks and overgrowth of faces found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 12/8/1964
REGISTERED LAND SURVEYOR