

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MACKINAC CO.

4 CORNERS

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>43</u> N. <u>9</u> R. <u>K</u> W.		<u>B-3, I-3, K-3</u>
2. PROPERTY CONTROLLING IN SECTION <u>2</u> , T. <u>43</u> N. <u>9</u> R. <u>K</u> W.		<u>2</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____ , T. _____ N. _____ R. _____ E. _____ W.		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6-19 & 6-30 & 7-14, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- B-3 South 1/4 Corner of Section 2. OBT'S: Tam. 10", S34°E, 27 lks. & Cedar 5", N45°W, 29 lks.
- I-3 S.W. Sec. Cor. of Section 2. OBT'S: Hemlock 10", S65°E, 57 lks. & Beech 10, N100W, 29 lks.
- K-3 S.E. Sec. Cor. of Section 2. OBT'S: B. Ash 8, N25°E, 19 lks. & Y. Birch 12, S40°W, 33 lks.
- 2 East 1/16 Cor. on North side of Section 2. Not prev. set.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- B-3 Set corner at found 2" Iron Pipe set by M. Schaaf R.L.S. Found remains of Tamarack Stump S34°E, 17.8'.
- I-3 Witness corner as set by M. Schaaf R.L.S. Found remains of Hemlock Stump, S65°E, 37.6'.
- K-3 This corner set by single proportionate measure from two Irons on North side of Gilchrist Plat. Distances North, East, and West compare well with the originals.

2 Cor. set M.P.O.L. between North 1/4 Corner and N.E Section Corner of Section 2.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|----------------------------|---|
| B-3 DNR Inside 2" Pipe | K-3 DNR Monument |
| 5" B. Ash, N44°W, 1.0' | 1 1/2" Pipes, S65°E, 33.5 & N40°E, 13.4' |
| 6" Cedar, S68°E, 37.4' | 8" Cedar, S41°E, 8.85' |
| 10" Cedar, S49°E, 13.4' | 8" Cedar, S23°W, 11.5' |
| 8" Cedar, S38°W, 27.2' | 8" W. Birch, S70°W, 12.0' |
| I-3 DNR next to Fence Iron | 2 1" Pipe w/plastic RLS Cap buried West rut road. |
| 6" W. Pine, S64°W, 33.4' | 24" W. Pine, N69°E, 39.05' |
| 6" W. Pine, N24°W, 66.7' | 5" Spruce, S3°E, 23.5' |
| 5" W. Pine, N27°E, 79.3' | 14" W. Birch, S65°W, 43.9' |
| 6" W. Pine, S88°E, 56.5' | 24" W. Pine, N22°W, 57.7' |
| | 3/4" Pipe, S28°W, 10.6' |

SIGNED BY Gerald L. Wiggins
Gerald L. Wiggins
SURVEYOR'S MICHIGAN REGISTRATION NO. 23521

DATE 9-10-86

