

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Mackinac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>20</u> T <u>43N</u> R <u>10W</u> _____ S <u>20</u> T <u>43N</u> R <u>10W</u> _____ S _____ T _____ R _____	<u>10</u> <u>11</u> _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 11 09/30/2009 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 20) South 1/16 corner between Sections 19 and 20. Not established in the original survey.

(11-Sec. 20) Southwest 1/16 corner, Section 20. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 20) Established the corner midway and on the Section line between Section corner 1316.03'
south and Quarter corner 1316.03' north. The position for the corner falls in the centerline of a N-
S gravel road.

(11-Sec. 20) Established the corner at the intersection of straight lines connecting opposite 1/16
corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) Set 5/8"x18" rebar with plastic MDNR cap
6" below gravel surface of N-S road.
Set measuring nail with MDNR tag in the side of:
6" Cedar N62W 72.1'
7" Spruce S62E 25.77'
7" Cedar S74W 36.33'
15" Spruce N68W 37.49'
Bearings are magnetic.

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Cedar S40W 17.9' mrkd "SW1/16 BT"
6" Balsam N08E 21.2' do
11" Cedar S73W 26.1' do
12" Cedar N60W 14.77' do
Bearings are magnetic.

Signed by

Stephan J. Szyszkoski

Date

10/13/2009

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

