FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 2 Corners

Mackinac Co.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	т. <u>43 ж.,</u> к. <u>11 ж</u>	E-5, E-6	
2. PROPERTY CONTROLL- ING IN SECTION—	,T S., R E		·
3. MISCELLANEOUS PROPERTY IN SECTION —	,T, N. R E		
4. LOT NO , RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AN

David B. Eabbitt _, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, 6-15-, 1982, established, the corner points mentioned in lines 1 and 2 above were, in a field survey on._____ re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on______, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- Section Corner 8-9-16-17, set by silly D. Euckler, 5-20-71. 10" W. Spruce, N72°W, 40.0' & 14" W. Spruce, S68 W, 40.0'.
- 1/4 cor. on East side of Section 17. Wood Post, Spruce 8", S40°W, 8 lks. & Cedar 6", N40°E, 38 1ks.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- Re-set corner and marked new witt. as set by Billy D. buckler, R.L.S.
- Corner set M.P.O.L. between NE section corner and SE section corner of section 17.
 - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - D.N.R. Monument. New Bearings: 1" pipe turied in center line of road. . E-5 New Bearings:

7" Aspen,

6" Cedar, N77°E, 42.81

12" Spruce, N39°B, 67.71

8" Spruce, \$89°W,

12" R. Pine, S76 W, 71.9" 6" Cedar, N59°W, 41.01 8" R. Pine, N40°W, 56.3' 6" Cedar. S63°E, 39.7'

SIGNED BY

SURVEYOR'S MICHIGAN REGISTRATION NO._

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE